

Attention: One or more violations have been cited on this report.

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name PITTMER, RUSSELL		Inspector's Signature <i>Russ Pitmer</i>			Inspector's ID No. 00538	Report No. 21	Date yy mm dd 2015 08 11						
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1801 WEST 39TH ST. BLDG D VANCOUVER WA 98660				R/C R	Division NW	RR/Co. Representative (Receipt Acknowledged) Name KIM OHS Title ROADMASTER Email KIM.OHS@BNSF.COM Signature _____							
From: City VANCOUVER		Codes 2370	Destination City & County			Codes 2370	From Latitude						
State WA		53	City VANCOUVER			2370	From Longitude						
County CLARK		C011	County CLARK			C011	To Latitude						
Mile Post: From 0000.00 To 0000.00		Inspection Point VANCOUVER YARD				To Longitude							
Activity Code:	TOY	YTW	2180	DER	RWP	CWRP	2170						
Units:	22	2	1	2	1	1	1						
Sub Units:	0	0	1	0	1	0	1						
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	0000.00	Y	T	213	0135	B1	10	1	4601N	N	N	1	TOY
Description IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL. (WEST RAIL).													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	0000.00	Y	T	213	0127	A2	10	1	4601N	N	N	1	TOY
Description INSUFFICIENT FASTENERS IN A TRACK SEGMENT.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	0000.00	Y	T	213	0135	B1	10	1	4602N	N	N	1	TOY

Description
IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	0000.00	Y	T	213	0133	A4	10	1	4602N	N	N	1	TOY

Description
LOOSE, WORN, OR DEFECTIVE CONNECTING ROD FASTENING.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	0000.00	Y	T	213	0133	A15	10	1	4603N	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED. (JOINT BAR BEHIND FROG).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	0000.00	Y	T	213	0133	A15	10	1	4604N	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED. (JOINT BAR BEHIND FROG).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	0000.00	Y	T	213	0135	E1	10	1	4605N	N	N	1	TOY

Description
SWITCH STAND OR SWITCH MACHINE INSECURE OR OPERABLE WITH EXCESSIVE LOST MOTION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	0000.00	Y	T	213	0133	A15	10	1	4605N	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED. (JOINT BAR BEHIND FROG).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	0000.00	Y	T	213	0133	A15	10	1	4606N	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED. (MISSING CLIP).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	0134.02	Y	Y	213	0109	B3	10	1	B LEAD 2	N	N	1	YTW

Description
NO EFFECTIVE SUPPORT TIES WITHIN THE PRESCRIBED DISTANCE FROM A JOINT. (32" NORTH / 53" SOUTH).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	0134.80	Y	Y	213	0121	C1	10	1	B LEAD 2	N	N	1	YTW

Description
CENTER CRACKED OR BROKEN JOINT BAR (JOINTED TRACK)

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	0000.00	Y	T	213	0135	F	10	1	4602S	N	N	1	TOY

Description
THROW LEVER OPERABLE WITH SWITCH LOCK OR KEEPER IN PLACE.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	0000.00	Y	T	213	0135	B2	10	1	4602X	N	N	1	TOY

Description
EXCESSIVE LATERAL OR VERTICAL MOVEMENT OF SWITCH POINT. (EAST RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14	0000.00	Y	T	213	0103	D	10	1	4602X	N	N	1	TOY

Description
FOULED OR INSUFFICIENT BALLAST FAILING TO MAINTAIN PROPER GEOMETRY. (STOCK RAIL AND SWITCH POINT MOVING VERTICALLY).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
15	0000.00	Y	T	213	0133	A15	10	1	3940	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED. (CLIPS MISSING ON WEST JOINT).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
16	0000.00	Y	T	213	0135	E1	10	1	3940	N	N	1	TOY

Description
SWITCH STAND OR SWITCH MACHINE INSECURE OR OPERABLE WITH EXCESSIVE LOST MOTION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
17	0000.00	Y	T	213	0133	A12	10	1	3940	N	N	1	TOY

Description
LOOSE, WORN, OR MISSING FROG BOLTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
18	0000.00	Y	T	213	0133	A15	10	1	3940	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
19	0000.00	Y	T	213	0135	A1	10	1	3938	N	N	1	TOY

Description
STOCK RAIL NOT SECURELY SEATED IN SWITCH PLATES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
20	0000.00	Y	T	213	0135	B2	10	1	3938	N	N	1	TOY

Description
EXCESSIVE LATERAL OR VERTICAL MOVEMENT OF SWITCH POINT.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
21	0000.00	Y	T	213	0109	B2	10	1	3938	N	N	1	TOY

Description
CROSSTIES NOT EFFECTIVELY DISTRIBUTED TO SUPPORT A 39-FOOT SEGMENT OF TRACK.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
22	0000.00	Y	T	213	0133	A12	10	1	3938	N	N	1	TOY

Description
LOOSE, WORN, OR MISSING FROG BOLTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
23	0000.00	Y	T	213	0135	A1	10	1	3911	N	N	1	TOY

Description
STOCK RAIL NOT SECURELY SEATED IN SWITCH PLATES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
24	0000.00	Y	T	213	0115	A1	10	1	3911	N	N	1	TOY

Description
RAIL-END MISMATCH ON TREAD OF RAIL EXCEEDS ALLOWABLE. (MEASUREMENT A3/8THS).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
25	0000.00	Y	T	213	0135	B1	10	1	3913	N	N	1	TOY

Description
IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
26	0000.00	Y	T	213	0133	A9	10	1	3913	N	N	1	TOY

Description
LOOSE OR MISSING ADJUSTABLE RAIL BRACES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
27	0000.00	Y	T	213	0135	A1	10	1	3913	N	N	1	TOY

Description
STOCK RAIL NOT SECURELY SEATED IN SWITCH PLATES. (IMPROPER REPAIR)

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
28	0000.00	Y	T	213	0135	F	10	1	3913	N	N	1	TOY

Description
THROW LEVER OPERABLE WITH SWITCH LOCK OR KEEPER IN PLACE.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
29	0000.00	Y	T	213	0133	A12	10	1	3913	N	N	1	TOY

Description
LOOSE, WORN, OR MISSING FROG BOLTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
30	0000.00	Y	T	213	0135	B1	10	1	4516S	N	N	1	TOY

Description
IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL. (EAST RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
31	0000.00	Y	T	213	0135	B1	10	1	4516S	N	N	1	TOY

Description
IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL. (WEST RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
32	0000.00	Y	T	213	0135	H1	10	1	4516S	N	N	1	TOY

Description
UNUSUALLY CHIPPED OR WORN SWITCH POINT. (EAST RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
33	0000.00	Y	T	213	0135	D	10	1	4516S	N	N	1	TOY

Description
HEEL OF SWITCH INSECURE. (WEST RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
34	0000.00	Y	T	213	0133	A12	10	1	4516S	N	N	1	TOY

Description
LOOSE, WORN, OR MISSING FROG BOLTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
35	0000.00	Y	T	213	0135	B1	10	1	3920S	N	N	1	TOY

Description
IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
36	0000.00	Y	T	213	0133	A12	10	1	3925S	N	N	1	TOY

Description
LOOSE, WORN, OR MISSING FROG BOLTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
37	0000.00	Y	T	213	0135	B1	10	1	3031S	N	N	1	TOY

Description
IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
38	0000.00	Y	T	213	0135	B2	10	1	3031S	N	N	1	TOY

Description
EXCESSIVE LATERAL OR VERTICAL MOVEMENT OF SWITCH POINT.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
39	0000.00	Y	T	213	0135	H1	10	1	3032S	N	N	1	TOY
Description UNUSUALLY CHIPPED OR WORN SWITCH POINT.													
Seal Applied		Seal Removed		Hazard Class		UN/NA ID							
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:					
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			
40	0000.00	Y	T	213	0121	F1	10	1	3032S	N	N	2	TOY
Description LOOSE JOINT BARS (JOINTED TRACK)													
Seal Applied		Seal Removed		Hazard Class		UN/NA ID							
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:					
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			
41	0000.00	Y	T	213	0135	B1	10	1	3033S	N	N	1	TOY
Description IMPROPER FIT BETWEEN SWITCH POINT AND STOCK RAIL. (WEST RAIL).													
Seal Applied		Seal Removed		Hazard Class		UN/NA ID							
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:					
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			
42	0000.00	Y	T	213	0135	B2	10	1	3033S	N	N	1	TOY
Description EXCESSIVE LATERAL OR VERTICAL MOVEMENT OF SWITCH POINT. (WEST RAIL).													
Seal Applied		Seal Removed		Hazard Class		UN/NA ID							
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:					
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 00538	Report No. 21	Report Date 8/11/2015
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
43	0000.00	Y	T	213	0135	D	10	1	3033S	N	N	1	TOY

Description
HEEL OF SWITCH INSECURE. (WEST RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
44	0000.00	Y	T	213	0135	E2	10	1	3034S	N	N	1	TOY

Description
CONNECTING ROD INSECURE OR OPERABLE WITH EXCESSIVE LOST MOTION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
45	0000.00	Y	T	213	0133	A14	10	1	3034S	N	N	1	TOY

Description
LOOSE, WORN OR MISSING GUARD RAIL CLAMPS, WEDGE, SEPARATOR BLOCK, END BLOCK, OR OTHER COMPONENTS. (WEST GUARD RAIL).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
46	0000.00	Y	T	213	0133	A15	10	1	3034S	N	N	1	TOY

Description
TURNOUT OR TRACK CROSSING FASTENINGS NOT INTACT OR MAINTAINED. (IN FRONT OF FROG).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No 00538	Report No. 21	Report Date 8/11/2015
----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
47	0000.00	Y	T	213	0135	A1	10	I	3922S	N	N	1	TOY

Description
STOCK RAIL NOT SECURELY SEATED IN SWITCH PLATES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
48	0000.00	Y	T	213	0135	B2	10	I	3921S	N	N	1	TOY

Description
EXCESSIVE LATERAL OR VERTICAL MOVEMENT OF SWITCH POINT.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
49	0000.00	Y	T	213	0133	A12	10	I	3921S	N	N	1	TOY

Description
LOOSE, WORN, OR MISSING FROG BOLTS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
50				ROR		H899				N	N	1	

Description
GENERAL RCO/RCL RULES; OTHER NONCOMPLIANCE RELATING TO RCL/RCO OPERATIONS AND PROCEDURES NOT LISTED AND NOT COVERED UNDER FEDERAL REGULATIONS. (MACHINE WAS LEFT UNMANNED WITH KEYS IN THE IGNITION.)

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?